

Dear Mr Hudson

Further to our recent telephone conversation, please find below written clarification of our position regarding engine damage caused by water ingress.

Please be advised that your motorcycle is capable of being ridden through water, however, it does depend on how deep the water is and the speed at which the bike is travelling. The deeper the water or faster the travelling speed, then the greater the displacement of water and so meaning a higher chance of water ingressing to the engine through the air box intake pipe.

When riding through standing water, please bear in mind that the wading depth of the bike is governed by the height of the air box intake pipe.

In closing, we hope that this response helps to clarify the matter for you.

Yours sincerely

